

Community Living Arrangement Inspection Report Summary

Kirk Road

85 Kirk Road Hamden, CT 06517

R-1202

ARC of Meriden-Wallingford

Inspection Date: Tuesday, November 27, 2012

DDS Region: South

Inspection Type: Initial

Inspection Report Citations Were Reported In The Following Regulatory Areas:

Regulatory Category

17a-227-11	Physical Requirements
11c	Home safety inspections
11e	Furnishing good repair